

- 2 -

04645.1072

In the Specification:

The paragraph beginning on page 4, line 16 has been amended as follows:

~~Fig. 14.~~ Fig. 14 is a cross-sectional view along line 14-14 of Fig. 13.

- 3 -

04645.1072

The paragraph beginning on page 15, line 4 has been amended as follows:

A pin 266 having the shape of the lead of a co-axial conductor is positioned in the second mold portion 254 received in the respective terminal blocks 262 and 264. Inserts 268 and 270 are supported on the second mold portion 254 abutting the shaped pin 266 from the back of the ~~molded~~ mold portion, i.e., that portion of the mold lying in the plane of the paper for Fig. 11 and extending toward the reader. These inserts 268, 270 coincide with passageways 182, 184 for the header assembly 150. The second mold portion 254 is then secured to the first mold portion 252 to provide a cavity having the shape of the to be manufactured header assembly. In that respect, the header assembly is formed laying on its side such that surface 272 of the second mold portion 254 forms the front wall 94 of header assembly 10 while surface 274 of the first mold portion 252 forms the back wall 96 thereof. Mold structure 276 forms the suture openings of the various header assemblies.